

Maryland Historical Trust State Historic Sites Inventory Form

Survey No. T-843

Magi No.

DOE ___yes ___no

1. Name (indicate preferred name)

historic

and/or common Bayshore Cottage

2. Location

street & number Bayshore Drive ___ not for publication

city, town Tilghman ___ vicinity of congressional district Fifth

state MD county Talbot

3. Classification

Category	Ownership	Status	Present Use	
___ district	___ public	<input checked="" type="checkbox"/> occupied	___ agriculture	___ museum
<input checked="" type="checkbox"/> building(s)	<input checked="" type="checkbox"/> private	___ unoccupied	___ commercial	___ park
___ structure	___ both	___ work in progress	___ educational	<input checked="" type="checkbox"/> private residence
___ site	Public Acquisition	Accessible	___ entertainment	___ religious
___ object	___ in process	<input checked="" type="checkbox"/> yes: restricted	___ government	___ scientific
	___ being considered	___ yes: unrestricted	___ industrial	___ transportation
	<input checked="" type="checkbox"/> not applicable	___ no	___ military	___ other:

4. Owner of Property (give names and mailing addresses of all owners)

name Gilbert K. and Louise G. Frampton

street & number Bayshore Drive telephone no.:

city, town Tilghman state and zip code MD 21671

5. Location of Legal Description

courthouse, registry of deeds, etc. Talbot County Clerk of Court liber 597

street & number Talbot County Courthouse folio 596

city, town Easton state MD

6. Representation in Existing Historical Surveys

title

date ___ federal ___ state ___ county ___ local

depository for survey records

city, town state

7. Description

Survey No. T-843

Condition

☐ excellent
☐ good
☒ fair

☐ deteriorated
☐ ruins
☐ unexposed

Check one

☐ unaltered
☒ altered

Check one

☒ original site
☐ moved date of move _____

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

The Bayshore Cottage is located on the west side of a dirt road on the south side of Bayshore Drive. The house faces north with the principal gable oriented on an east/west axis.

Built between 1890-1910, this two-story, frame house is supported by a cement foundation and sheathed in white weatherboard with green trim. The roof is covered in asphalt shingles.

The north (main) facade has three bays with a central door flanked by two-over-two sash windows. There are two two-over-two sash windows on the second floor. A one-story, gable roofed addition is attached to the east end of this structure and has one two-over-two sash window on the north side. A second and more recent addition clad in aluminum siding and covered with a gable roof is connected to this first addition.

The east elevation is blind with an interior chimney stack piercing the gable roof of the main structure.

The south elevation is identical to the north with a central door flanked by two two-over-two sash windows on the first story, and a pair of two-over-two sash windows on the second story. There is a second door on the south elevation through the first addition.

The west elevation is blind.

8. Significance

Survey No. T-843

Period	Areas of Significance—Check and justify below			
<input type="checkbox"/> prehistoric	<input type="checkbox"/> archeology-prehistoric	<input type="checkbox"/> community planning	<input type="checkbox"/> landscape architecture	<input type="checkbox"/> religion
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> archeology-historic	<input type="checkbox"/> conservation	<input type="checkbox"/> law	<input type="checkbox"/> science
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> agriculture	<input type="checkbox"/> economics	<input type="checkbox"/> literature	<input type="checkbox"/> sculpture
<input type="checkbox"/> 1600-1699	<input checked="" type="checkbox"/> architecture	<input type="checkbox"/> education	<input type="checkbox"/> military	<input type="checkbox"/> social/
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> art	<input type="checkbox"/> engineering	<input type="checkbox"/> music	<input type="checkbox"/> humanitarian
<input checked="" type="checkbox"/> 1800-1899	<input type="checkbox"/> commerce	<input type="checkbox"/> exploration/settlement	<input type="checkbox"/> philosophy	<input type="checkbox"/> theater
<input type="checkbox"/> 1900-	<input type="checkbox"/> communications	<input type="checkbox"/> industry	<input type="checkbox"/> politics/government	<input type="checkbox"/> transportation
		<input type="checkbox"/> invention		<input type="checkbox"/> other (specify)

Specific dates

Builder/Architect

check: Applicable Criteria: ☐ A ☐ B ☒ C ☐ D
and/or

Applicable Exception: ☐ A ☐ B ☐ C ☐ D ☐ E ☐ F ☐ G

Level of Significance: ☐ national ☐ state ☒ local

Prepare both a summary paragraph of significance and a general statement of history and support.

Built between 1890-1910, this two-story, single pile frame structure is one of a collection of simple vernacular dwellings on the west side of Route 33 in the village of Tilghman. This building is in poor repair, but retains much of its original exterior fabric. It also has the distinctive green and white color scheme of so many Tilghman buildings. An almost identical house sits to the north of this structure on the same dirt road.

Survey No. T-843

T-843
Bayshore Cottage
Tilghman Island Quadrangle





BAY SHORE LOFTAGE

T-843

TUGHERMAN ISLAND, TALBOT COUNTY, MD

NORTHEAST ELEVATION

E. HUGHES, PHOTO

8.1.70